

5.0 Maintenance of CCTV Cameras installed at GSL perimeter

5.1 Brief Introduction:

Vigilance executives carried out Surprise Inspection of CCTV cameras installed at places of public dealings /along the GSL perimeter to verify that these cameras are operational.

5.2 Background:

During the inspection, it was observed that out of total 19 CCTV cameras installed for monitoring the GSL perimeter, 07 cameras are found to be non-operational. Also the resolution of the CCTV cameras is only 2 mega-pixels which is not adequate for surveillance purpose.

Further it was observed that there is no CCTV camera installed at crucial locations involving public dealings and at weighbridges.

5.3 Implementation:

The following Systemic improvements were suggested for implementation:

- a) All faulty CCTV cameras to be replaced to resolve the operational issue.
- b) To ensure placement of AMC contract with the CCTV vendors for proper up-keeping of the CCTV surveillance system in GSL.

5.4 Impact and Benefits:

By implementing the above suggestions, proper surveillance of the GSL perimeter will be achieved which will eliminate the chances of probable theft / any other unforeseen circumstances related to security of the organization.